

Manufacturer-related Product Qualification

MPQ in accordance with DBS 918 005 [EXC3DB]

Technical specification for the construction of railway bridges and other engineering structures, in keeping with the scope of Guideline 804.

The manufacturer: (party placing the products on the market) MAURER SE, Frankfurter Ring 193, 80807 München, Germany

and its manufacturing works:

(plant)

Maurer Söhne Genlesme Derzleri Sanayi ve Ticaret Limited Sirketi, Saipler Mahallesi Philsa Cad. No: 192/A, 35860 Torbali / Izmir, Turkey

are qualified for individual fabrication of the following steel structures and components:

1.2 Components for steel-concrete	ID								
☑ ! 2.1 Bridge bearings including ☑ ☑ ! 2.2 Bearings for special bridges ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	-								
2.3 Bridge deck transition structures in accordance with Guideline 804.5202									
2.7.1 Standardised and complex support structures for provisional and railway bridges in accordance with Guideline 804.4110, Section 4 (4)									
2.7.4 Stiffeners in accordance with Guideline 804.4110, Section 4 (5)									
2.8 Control bar structures									
2.12 Support structures for transfer tables, turntables, elevated tracks and plant, machinery and equipment subjected to rail traffic	100								
2.16 Welded fastening of support points of the overhead line, of noise barrier posts and other welded steel structures on steel bridges									
Restrictions: The welding qualification (off-site manufacturing) for components is restricted to a mass of 20 t per individual component.									
An increase of the individual mass (off-site manufacturing) is possible up to 30 t following submission of a separate technol concept.	ogy								
Qualification to perform welding and corrosion protection work as part of maintenance, repair and/or installation work. Observations and warranty requirements. See above 2.1+2.2 Qualification to perform welding and corrosion protection work as part of maintenance, repair and/or installation work. Observations and/or approval within the meaning of the specified regulations.	rve								
no further entries									

Manufacturer's mark used: 00216_DB-HPQ918005_Maurer Tor-G05-2025

This certificate confirms that compliance with the requirements of DBS 918 005 for the above-mentioned types of steel structures and components has been verified as part of this manufacturer-related product qualification (documentary check and site inspection).

Valid until: Repeat qualification for a limited period ending on 22 May 2025

Start: 22 May 2019

Valid until: For restriction see above.

A valid certification in accordance with DIN EN 1090-1 WPK (conformity of internal production control), welding certification in accordance with DIN EN 1090-1 Table B.1 for welding steel structures in accordance with DIN EN 1090-2 (EXC 3 or EXC4) is required for this qualification to be valid in keeping with DBS 918005 EXC3DB. This qualification is valid for as long as the provisions of DBS 918005 mentioned above in conjunction with DIN EN 1090, the manufacturing conditions and/or the internal production control system have not significantly changed (see page 2 General provisions).

See reverse side of this certificate for general provisions

Deutsche Bahn AG

Beschaffung Infrastruktur (Infrastructure Procurement) Quality assurance

Berlin, 12 July 2022

p.p. Mans-reter illum p.

Dr. A. Eghdam



General provisions:

1.	Deutsche Bahn AG, Infrastructure Procurement, Quality Assurance, must be informed in due time if persons mentioned in this certificate who are responsible for the implementation of the MPQ requirements leave the company, or if the conditions for obtaining the MPQ have significantly changed. Deutsche Bahn AG, Infrastructure Procurement, Quality Assurance, can request a repeat inspection of welding operations to be carried out if necessary.
2.	
2	pense at any time.

whi imr 4. If th Pro 5. Afte EX 109 me	ich the certificate w mediately remove a ne MPQ is to be ext ocurement, Quality er a recertification, C3DB must provide	vas granted have all issued MPQ cerended, the manuf Assurance, at least significant change a Deutsche Bahn vion control and welding and we	changed or if the re tificates that are pul acturer must coordin st two months prior t ss to the certificates AG, Infrastructure Pong - EXC 3 or EXC4).	quirements are not blicly available inclunate the dates and to the expiry of the (e.g. vSAP), etc., throcurement, Quality	met. In case of a ding any reference erms of the exter validity of the MP de holder of the q Assurance, with f the persons res	a withdrawal, the ma ces to their ownershi ision with Deutsche Q or before the date ualification in accord a proof of the validit	Bahn AG, Infrastructure of the next inspection. lance with DBS 918005 y of the certification (EN enting the MPQ require-
A c no and inv	compliance review in changes have occu ce review be skippe alidate or limit the v	s carried out if, for urred and the man ed. Agreeing on a alidity of the MPQ	example, the requi ufacturing process l date to conduct the	rements change or has been continuou compliance review DBS 918005 EXC3	there are delays sly monitored, th or skip the comp DB. If the validity	e manufacturer can liance review for a ju	findings of the audit. If request that the compli- istified reason does not of the review, Deutsche
	DE	9				[06]	
Comm	ents:	(DB)	D8			08	
1. Process	ses presented by	the manufactur	er for MPQ:				
Own p	rocesses:				tracted proce		
\boxtimes	Planning/sizing First-stage pro	51	g, milling, drilling, etc	11.251	Planning/sizin First-stage pro	g, design ocessing (sawing,	milling, drilling, etc.)
\boxtimes	Welding	DB		DB)	Welding	08	
	Thermal treatn		17)131		Thermal treatment/flame straightening Non-destructive testing (NDT)		
	Fasteners		DB	DB	asteners	DB)	
	Corrosion prot	ection			Corrosion prof	tection	
Comm	Assembly			Comme	Assembly	(824)	
Commi	ent: None		(08)	Comme	nt: None	DB	
				[DB]	[DB]		
	Services provide Types of services:	<mark>ded based on a</mark> None	contract for wor	rk and services/a	a subcontracto	or agreement (see	DBS 918005, Item 5.3)
[DB]	[DI	None	[08]	[08]	[08]	[08]	
	08	(58)					
	responsible for ir a Sungur, born 09		requirements of t	the MPQ:	[08]	(08)	
in rune	a Sungui, boin o.	January 1575	(DB)			DB)	(08)

Representative of the person responsible for implementing the requirements of the MPQ: Mr Wajahat Hussain, born 13 August 1986